



Date of Issuance: October 18, 2023

Reference Control No.: WMD-2023-SSC-COI-0655

Certificate of Interconnection

- Direct Interconnection (Separate Sewer) Indirect Interconnection (Combined Sewer)

MAYNILAD WATER SERVICES, INC., as the Concessionaire of the Metropolitan Waterworks and Sewerage System (MWSS) for the West Zone Service Area, issues this Certificate to:

MAPUA INSTITUTE OF TECHNOLOGY

(Private- College/ Universities)

*Address: Mapua Intramuros Muralla St., Intramuros, Manila City
CAN: 55844273*

Wastewater from the above establishment is conveyed to the Tondo Sewage Pumping Plant preliminary treatment before it is pumped to a 5.9 km. ocean outfall with diffusers. Said facility is operating with Discharge Permit No. DP(R)-25a-2021-02559 issued by LLDA on September 9, 2021 and valid up to July 3, 2024.

The quality of wastewater from this establishment shall comply with the MWSS Pre-treatment Standards for all Establishments discharging Non-domestic Effluents to the MWSS Sewerage System (the "Guidelines"). Failure to do so shall result in the revocation of this Certificate.

This Certificate is issued upon the request of the above-named establishment, and is valid for a period of one (1) year from its date of issuance.

Issued by:

Apollo C. Tiglao
Head, Wastewater Management Division
Maynilad Water Services, Inc.

Dye Test Inspection Report




Maynilad

Wastewater Management Division – Sewer Network Management Department

Account Name : MAPUA INSTITUTE OF TECHNOLOGY Date : OCT 18, 2023
 Address : MAPUA INTRAMUROS MURALLA ST. INTRAMUROS MANILA Time Started : 10:15 A.M
 Contract Account No. : 58044273 Time Finished : 12:30 P.M
 Establishment Name : MAPUA UNIVERSITY Rate Type : COMMERCIAL

- SCHOOL

SKETCH:



Inspector's Initial Findings:

- | | |
|---|---|
| <input checked="" type="checkbox"/> With Septic Tank | <input type="checkbox"/> With Drainage Enhancements (Year: _____) |
| <input checked="" type="checkbox"/> With Discharge Outlet | <input type="checkbox"/> With Road Improvements (Year: _____) |
| <input type="checkbox"/> With SSC Clean-out Box | <input type="checkbox"/> With Property Expansions (Year: _____) |
| | <input type="checkbox"/> With Change in Ownership (Year: _____) |

Nearest Sewer Manhole: _____ meters
 Nearest Sewer Line : _____ meters

Other remarks: DYE TESTED AT HOLDING TANK DISCHARGE OUTLET

Dye Test Results:

- Connected to Sewer line
 Connected to Sewer line but with leak
 Other remarks: DYE SEEN ON SMK

Recommendation:

- Retain Sewer Classification
 Repair of Sewer Connection
 Further Assessment
 Other remarks: FOR COI

Test Conducted by: [Signature]
M. GUTIERREZ, E. REYES
 Inspector's Signature over Printed Name

Date: OCT 18, 2023

Witnessed by: [Signature]
Jeffrey Madies
 Customer's Signature over Printed Name

Designation: Facilities Engineer
 Contact No.: 09192937247 / 0917109924
 Date: October 18, 2023